














 10 min	 1x	 Screwdriver (Not provided)
---	---	--


A  M4x30mm 8x	B  M4x50mm 6x	C  M3x15mm 12x	D  6x
---	---	--	---

1  1x	4  1x
2  2x	5  2x
3  4x	

1 	
B  M4x50mm 2x	D  2x



2




D



4x

3




B



M4x50mm

4x

4




C



M3x15mm

12x

5



A



M4x30mm

8x

6

